Dart Aerospace Ltd. Tuesday, 7/1/2008 2:34:29 PM Date User Kim Johnston **Process Sheet** Customer : CU-DAR001 Dart Helicopters Services **Drawing Name** : WEARPAD Job Number : 40191 Estimate Number : 12785 P.O. Number : D356411 Part Number This Issue : 7/1/2008 S.O. No. : D3564 REVD **Drawing Number** Prsht Rev. : NC : N/A Project Number : 11 First Issue Type : SMALL /MED FAB : D Drawing Revision : 39133 Previous Run Material Due Date : 7/16/2008 Written By Qty: 20 Um: Each Checked & Approved By Comment : Est Rev:A New Issue 07-03-08 ec Est Rev:B As per Rev C 07-07-09 JLM Est Rev C As per Rev D 07-09-09 JLM Verified By:EC Additional Product Job Number: Seq. #: Machine Or Operation: Description: 1.0 M304S16GA 304/316 063 Sheet Comment: Qty.: 1.4805 sf(s)/Unit Total: 29.6100 sf(s) M304S16GA Stainless steel sheet 0.063" thick Batch: 108156 2.0 WATER JET FLOW WATER JET Comment: FLOW WATER JET 1-Cut as per Dwg D3564 \*\*\*\*\*(D3564-1F)\*\*\*\*\* Dwg Rev: D HB 8-7-14 Prog Rev: D 2-Deburr if necessary HS8-7-14 30 QC2 INSPECT PARTS AS THEY COME OFF MACHINE 138-7-14 Comment: INSPECT PARTS AS THEY COME OFF MACHINE 40 QC8 SECOND CHECK

D CHECK

Comment: SECOND CHECK
5.0 BRAKE NC


NC BRAKE



Comment: NC BRAKE

Deburr if necessary

Form on Brake as per Dwg D3564 using Jigs DT and DT 3







Date: Tuesday, 7/1/2008 2:34:29 PM User: Kim Johnston	Process Sheet
Customer: CU-DAR001 Dart Helicopters Services	Drawing Name: WEARPAD
Job Number: 40191	Part Number: D356411
Job Number:	
Seq. #: Machine Or Operation:	Description :
6.0 QC5	INSPECT WORK TO CURRENT STEP
	(xento
Comment: INSPECT WORK TO CURRENT STEP	
Ensure joggle as per dwg D3429  7.0 LARGE FAB 1	LARGE FABRICATION RESOURCE 1
LANGET AB T	LARGE PARKICATION RESOURCE 1
Comment: LARGE FABRICATION RESOURCE 1	
Qty Description Batch	
A/R 2059B Hardcoat Weld hardcoat as per Dwg D3437	M108631
8.0 QC10	VISUAL INSPECTION OF GROUND WELDS
Comment: VISUAL INSPECTION OF GROUND WELD	05/04/02 (7/3)
9.0 QC5	INSPECT WORK TO CURRENT STEP
Comment: INSPECT WORK TO CURRENT STEP	08/04/22 413
10.0 POWDER COATING	POWDER COATING
M 10	06442 (13x)
Comment: POWDER COATING	
Powder Coat Grey Sandtex (Ref: 4.3.5.6) as	per QSI 005 4.3
START TIME: 8 19	E
OVEN TEMPERATURE: 320	m / 1057/
FINISH TIME: 01/10	111/2 08/07/22
11.0 QC3	NSPECT POWDER COAT/CHEMICAL CONVERSION
Comment: INSPECT POWDER COAT/CHEMICAL COM	IVERSION $08-07-22$
12.0 PACKAGING 1	PACKAGING RESOURCE #1
	(13x)
Comment: PACKAGING RESOURCE #1	
Identify and Stock FP -/ C	1 m. 1 08/0 7/22
	10 1 1



1 ucoudy, 11 112000 2.04.20 1 W

User:

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WEARPAD

Job Number: 40191

Part Number: D356411

Job Number:

Seq. #:

Machine Or Operation:

Description:

130

QC21


FINAL INSPECTION/W/O RELEASE.



Comment: FINAL INSPECTION/W/O RELEASE

Job Completion





DART AEROSPACE LTD	Work Order:	40191
Description: Wearshoe	Part Number:	D3564-11
Inspection Dwg: D3564 Rev: D		Page 1 of 1

## FIRST ARTICLE INSPECTION CHECKLIST

		- CILEGIALIO
X	First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
3.227	+/-0.010	3.239	*			
2.432	+/-0.010	2,439	*			
2.50	+/-0.030	2,50	*			
6.000	+/-0.010	6.004	*			
12.104	+/-0.010	12.104	×			
18.000	+/-0.010	18.000	ie			
18.00	+/-0.030	18.00	×			
9.00	+/-0.030	9.00	~			
11.50	+/-0.030	TATAL MESA				
0.300 x 0.300	+/-0.010	2	*			
Ø0.188	+0.005/-0.001	100001	×			
R0.375	+/-0.010	,375				
0.063	+/-0.010	1068	*			
			4.			

Measured by:	0	A. B.			
Date:	HS 7 11	Audited by:		Prototype Approval:	N/A
Date.	8-1-14	Date:	Sel07/14	Date:	N/A

	Rev	Date	Change			
	Α	07.09.06	New Issue	Revised by Appro	ved	
			Dwg Rev updated	KJ/JLM		
10		V	Dwg Nev updated	KJ/EC/DD		



